

Cleaning anodized aluminum



01. **Wash the surface** with warm water and a **pH-neutral cleaner** (5–8) using a soft cloth or synthetic brush.
02. **Gently scrub** without applying excessive pressure.
03. **Rinse thoroughly** with clean water to remove all residue.
04. **Dry immediately** with an absorbent cloth to prevent streaks.



Absolutely avoid; strong acidic or alkaline products, steel wool, abrasive pads, or overly powerful pressure washing.

